

Mulberry Street

Tax Parcel #: 3-35-8.07-298

CRS # Parish House: 290.743 contributing

Property Address: 211 Mulberry Street

Name of property: Saint Peter's Episcopal Church

Date of property: early 20th C.

Historic district: yes

Architectural details: Cross plan with square tower. cross gable roof. double-hung, eight-over-eight windows. moderate eave overhang. arch window over window tower. weather board siding. transom light over door.

Notes from secondary resources: Original nomination #100. rests on a cement-block foundation and is part of the St. Peter's Church complex.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-295.1

CRS # Commercial building: 290.749 non-contributing

CRS # Garage: 290.750 contributing

Property Address: 212 Mulberry Street

Name of property: n/a

Date of property: modern building / early 20th c for garage

Historic district: yes

Architectural details: one-story cottage. double-hung, six-over-six window with shutters. wood shingle exterior. slight eave overhang. rear porch (corner) with turn-post supports. shingle roof. one-car garage with vertical board siding and gable roof.

Notes from secondary resources: Original nomination #95. two section gable roof. 1992 survey lists as a commercial building. now a dwelling.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.08-295

CRS # Dwelling: 290.747 contributing

Property Address: 216-214 Mulberry Street

Name of property: Old Bethel church

Date of property: c. 1790

Historic district: yes

Architectural details: side gable roof. shingle exterior. double-hung, nine-over-nine windows.

Notes from secondary resources: Original nomination #96. moved from Third and Market Streets in 1818 to Mulberry and Church Streets. In 1870 moved again to present location on Mulberry and Third Streets. "The Traveling Church"

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-243

CRS # Dwelling: 290.651 contributing

Property Address: 302 Mulberry Street

Name of property: n/a

Date of property: c. 1840

Historic district: yes

Architectural details: two-story, five-bay dwelling. side gable roof. double-hung, six-over-six windows with shutters. shingle exterior. two-story rear wing. two, shingle-story lean-to additions: one to the north east, the other to the southwest.

Notes from secondary resources: Original nomination #65. built in several parts from the second quarter of the 19th century. The main block consists of two distinct sections: the northeast fenestration with three bays, two of which are doors, and the southwest section which has two bays, both of which are windows.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-205

CRS # Dwelling: 290.599 contributing

Property Address: 303 Mulberry Street

Name of property: n/a

Date of property: modern

Historic district: yes

Architectural details: side gable roof. wide eave overhang. wrap-around, wide-eave

Mulberry Street

visor overhang. paired casement windows. wood shingle siding. two bays.  
Notes from secondary resources: Original nomination #102.  
Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-206

CRS # Dwelling: 290.600 contributing

Property Address: 305 Mulberry Street

Name of property: n/a

Date of property: late 19th c.

Historic district: yes

Architectural details: five-rank, symmetrical facade. side gable roof. pediment window surround. door surround with side and transom lights. wood shingle exterior. double-ridge, interior chimneys. double-hung, two-over-two windows.

Notes from secondary resources: Original nomination #103. 1992 survey indicates a Victorian porch - there is none in view. either it is gone or on a part of the house that is not visible from the street.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-207

CRS # Dwelling: 290.601 contributing

Property Address: 307 Mulberry Street

Name of property: Anna Eliza Baker House

Date of property: 1874

Historic district: yes

Architectural details: Folk Victorian home with brick foundation. full-width porch with decorative brackets and center-gable roof. turn-spindle porch posts and balustrade. three-light transom light in door surround. blank-pane, double-hung windows. side gable roof with decorative brackets. weather board siding with corner boards.

Notes from secondary resources: Original nomination #104. one of the few frosted, cut-glass doors in Lewes.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-242

CRS # Dwelling: 290.650 contributing

Property Address: 308 Mulberry Street

Name of property: Baily Art West House

Date of property: early 19th c.

Historic district: yes

Architectural details: wood shingle exterior. double-hung, six-over-six windows with shutters. side gable roof with left side ridge interior chimney. first floor addition to left: one-story, side-gable roof with pediment dormer with metal roof. wooden window surround and door.

Notes from secondary resources: Original nomination #97. 1992 survey does not mention left-side addition.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-210

CRS # Dwelling: 290.602 contributing

CRS # Garage: 290.603 contributing

Property Address: 309 Mulberry Street

Name of property: n/a

Date of property: early 20th c.

Historic district: yes

Architectural details: cross gable roof. first floor three bay window. paired window with arch in first front gable. octagonal pattern in gable and in bay window. weather board siding with corner boards. double-hung, one-over-one windows.

Notes from secondary resources: Original nomination #105. since 1992 survey: new home replaced old dwelling and garage.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-242

Mulberry Street

CRS # Dwelling: 290.648 contributing  
CRS # Outbuilding: 290.649 contributing  
Property Address: 310 Mulberry Street  
Name of property: n/a  
Date of property: early 19th c - dwelling / mid 19th c - outbuilding  
Historic district: yes  
Architectural details: sits far back from street. wood shingle exterior. two-rank facade. slight eave overhangs. double-hung, six-over-six windows. shutter-like door with wooden door surround.  
Notes from secondary resources: Original nomination #97.  
Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-211  
CRS # Dwelling: 290.604 contributing  
CRS # Outbuilding: 290.605 contributing  
CRS # Shed: 290.606 contributing  
Property Address: 311 Mulberry Street  
Name of property: n/a  
Date of property: late 19th c - dwelling / early 20th c for others  
Historic district: yes  
Architectural details: side-gable roof with double-ended interior ridge chimneys. five-bay facade. double-hung, nine-over-nine sash windows with decorative arched surrounds. partial-width porch with scroll-sawn bracket balustrade and shed roof.  
Notes from secondary resources: Original nomination #106. no domestic outbuilding or shed as described in 1992 survey. no mention of rear addition with full facade porch in 1992 survey. possible a one-car garage or shed.  
Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-214  
CRS # Dwelling: 290.607 contributing  
Property Address: 313 Mulberry Street  
Name of property: Purnell Norman House  
Date of property: late 18th c.  
Historic district: yes  
Architectural details: side gambrel roof with ridge interior brick chimney. shed-roof dormer with double-hung, six-over-six sash window. three-bay facade. shutter-like door. wood shingle exterior. rear addition: one-story, gable-roof addition and a two-story addition.  
Notes from secondary resources: no mention of rear addition in 1992 survey.  
Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-241  
CRS # Dwelling: 290.646 contributing  
CRS # Garage: 290.647 non-contributing  
Property Address: 314 Mulberry Street  
Name of property: n/a  
Date of property: late 19th c - dwelling / modern garage  
Historic district: yes  
Architectural details: three-bay, two-story dwelling. side-gabled, metal roof. two-over-three fenestration. double-hung, six-over-six windows with shutters. pent visor around first floor. partial-width porch with turn-spindle supports and square balustrade. vinyl shingle siding.  
Notes from secondary resources: n/a  
Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-215  
CRS # Dwelling: 290.608 contributing  
Property Address: 315 Mulberry Street  
Name of property: n/a  
Date of property: late 19th c.  
Historic district: yes  
Architectural details: side gable roof. two story and five bay. pediment entry visor. double-hung, two-over-two sash windows. three-pane transom light in door

Mulberry Street

surround. wooden window surround. double-sided interior ridge chimneys.  
Notes from secondary resources: Original nomination #108. Since 1992 survey: no porch.  
Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-240

CRS # Dwelling: 290.644 contributing  
CRS # Outbuilding: 290.645 contributing  
Property Address: 316 Mulberry Street

Name of property: n/a

Date of property: c. 1880

Historic district: yes

Architectural details: three-bay, two-story dwelling. full-width porch with chamfered posts and decorative brackets. double-hung, two-over-two windows with shutters. transom and side lights in door surround. eight-pane front door. left side interior ridge brick chimney. moderate eave overhangs with decorative brackets. wavy asbestos siding.

Notes from secondary resources: One-story, shed-roofed addition filling in the ell on wing's southwest elevation. on wing's northeast elevation is a one-story bay window.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-239

CRS # Dwelling: 290.642 contributing  
CRS # Garage: 290.643 contributing  
Property Address: 318 Mulberry Street

Name of property: n/a

Date of property: c. 1875

Historic district: yes

Architectural details: two-story dwelling with five-bay facade. side-gable roof with left side exterior brick chimney. partial porch with hipped roof. scroll sawn decorative balustrade and decorative brackets in porch. transom light in door surround. double-hung, six-over-six windows with shutters. moderate eave overhangs. shingle roof and weather board siding.

Notes from secondary resources: Original nomination #99. there are interior chimneys on the northeast and wing's gable end. one-story, shed-roof addition filling the southwest side of the "T" and wrapping around the wing's gable end.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-216

CRS # Dwelling: 290.611 non-contributing  
Property Address: 321 Mulberry Street (might be 317 Mulberry St.)

Name of property: n/a

Date of property: modern

Historic district: yes

Architectural details: one-story cottage. front gable roof. both side sw/white shed dormer. moderate eave overhangs. shutters on palladian windows. brick exterior. exposed rafter porch with square supports.

Notes from secondary resources: modern brick bungalow.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-238

CRS # Dwelling: 290.640 contributing  
CRS # Garage: 290.641 contributing  
Property Address: 324 Mulberry Street

Name of property: n/a

Date of property: c. 1885

Historic district: yes

Architectural details: two-story, five-rank facade with third floor attic. center-gable roof with pointed arch window in gable. double-hung, two-over-two windows with shutters. partial-width porch with flat roof, chamfered supports, scroll-sawn decorative balustrade, and decorative brackets on posts. center ridge interior chimney.

Mulberry Street

Notes from secondary resources: Original nomination #99. one-story, shed-roofed addition on rear elevation and two, one-story, shed-roofed additions on wing's gable end. Since 1992 survey: no garage.  
Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-222

CRS # Dwelling: 290.613 contributing  
CRS # Storage: 290.614 non-contributing  
Property Address: 325 Mulberry Street

Name of property: n/a

Date of property: c. 1865 - dwelling / modern storage building

Historic district: yes

Architectural details: pediment door surround. cross gable roof. fixed windows first floor. double-hung window on second floor. aluminum siding with corner boards. storage building to right of facade.

Notes from secondary resources: Formerly a Methodist church, then a paint store, now a dwelling.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-238

CRS # Dwelling: 290.639 contributing  
Property Address: 326 Mulberry Street

Name of property: n/a

Date of property: c. 1935

Historic district: yes

Architectural details: side gable roof with shingles. two-story tower in front with metal roof. porch with square posts and metal roof.

Notes from secondary resources: Original nomination #99. The 1992 survey description describes the guest house more like a dwelling.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-223

CRS # Dwelling: 290.615 contributing  
CRS # Outbuilding: 290.616 contributing  
Property Address: 327 Mulberry Street

Name of property: n/a

Date of property: late 19th c.

Historic district: yes

Architectural details: three-rank, asymmetrical facade. double-hung, two-over-two windows with shutters. wooden window surround with slight sill. entry porch with flat roof, decorative brackets, and square posts. three-pane transom light in door surround. center slope interior chimney.

Notes from secondary resources: Original nomination #111

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-224

CRS # Dwelling: 290.617 contributing  
CRS # Guest Cottage: 290.618 contributing  
Property Address: 329 Mulberry Street

Name of property: n/a

Date of property: c. 1925 - dwelling / c. 1940 - guest cottage

Historic district: yes

Architectural details: front gable roof form. side lights in door surround. three-bay facade with four-over-three fenestration. wood shingle siding. full-width porch with metal roof and square posts. double-hung, blank-pane windows. wide eave overhangs.

Notes from secondary resources: 1992 survey description does not match.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-236

CRS # Dwelling: 290.638 contributing  
Property Address: 330 Mulberry Street

Name of property: n/a

Mulberry Street

Date of property: c. 1900

Historic district: yes

Architectural details: three-rank, two-story dwelling. side-gable roof. wrap-around porch with balustrade. double-hung, six-over-six windows with shutters. aluminum siding. side bay door with single light flat transom.

Notes from secondary resources: Original nomination #99. flat roof addition filling in the ell on wing's northeast elevation.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-224

CRS # Dwelling: 290.619 contributing

CRS # Guest Cottage: 290.620 contributing

Property Address: 331 Mulberry Street

Name of property: n/a

Date of property: mid 19th c.

Historic district: yes

Architectural details: center-gable roof with steep pitch and arch pointed window in gable. weather board siding. one-story cottage. entry porch with pediment roof. three bays. double-hung windows.

Notes from secondary resources: Original nomination #112. Since 1992 survey, siding changed from aluminum to wood weather board.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-235

CRS # Dwelling: 290.636 contributing

CRS # Outbuilding: 290.637 contributing

Property Address: 334 Mulberry Street

Name of property: n/a

Date of property: c. 1900

Historic district: yes

Architectural details: side-gable, steep-pitch roof. five-bay, two-story dwelling. full-width, wrap-around to right porch with supports that are half turn spindle and half posts (concrete pedestals). double-hung, one-over-one windows. exterior chimney. double-door.

Notes from secondary resources: Original nomination #99. northeast side of rear elevation is one half story gable-roofed wing with the portions of earlier dwelling. on northeast side of the wing is a shed-roofed sun room, attached to which is a long, one-story gable-roofed summer kitchen.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-228

CRS # Dwelling: 290.621 contributing

Property Address: 335 Mulberry Street

Name of property: n/a

Date of property: late 19th c.

Historic district: yes

Architectural details: five-bay, two-story dwelling. side-gable roof. left side brick exterior chimney. pediment window surround. double-hung, two-over-two windows. three-pane transom and side lights. board and batten door. brick foundation.

Notes from secondary resources: Original nomination #113. exterior looks like wood shingle but 1992 survey described as narrow weather board paper covering.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-234

CRS # Dwelling: 290.634 contributing

CRS # Outbuilding: 290.635 contributing

Property Address: 336 Mulberry Street

Name of property: n/a

Date of property: c. 1925

Historic district: yes

Architectural details: pyramidal hipped roof form. hipped dormer. first-floor, full-width porch. fixed, five-over-five-pane window in dormer. second floor paired

Mulberry Street

windows, double-hung six-over-one. door has five sets of three lights. weather board siding.

Notes from secondary resources: Original nomination #99.  
Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-233

CRS # Dwelling: 290.622 contributing

CRS # Garage: 290.623 contributing

Property Address: 337 Mulberry Street

Name of property: n/a

Date of property: late 19th c. for dwelling

Historic district: yes

Architectural details: side-gable, metal roof with pediment dormer that has a stationary three-by-four-pane window. three-bay, two-story dwelling. double-hung, six-over-six windows. partial porch with metal shed roof. turn-spindle supports and balustrade. weather board siding with corner boards.

Notes from secondary resources: Original nomination #114. Since 1992 survey, garage converted into sunroom.

Street survey completed: August 2005

Tax Parcel #: 3-35-8.07-234

CRS # Dwelling: not available - cross reference 290.634-635, #336 Mulberry

Property Address: 338 Mulberry Street

Name of property: n/a

Date of property: not available

Historic district: yes

Architectural details: three-bay, two-story dwelling with side-gable roof. three pediment dormers with double-hung, six-over-six sash windows. full-width porch with a hipped, metal roof. double-hung, six-over-six sash windows with plain vinyl surround and shutters. paired windows on first floor with center door. wood shingle exterior.

Notes from secondary resources: no CRS # on record. cross reference, 336 Mulberry Street. needs a new survey.

Street survey completed: August 2005