

Beebe Avenue

Tax Parcel #: 3-35-8.11-122
CRS# dwelling: S. 290.368 contributing
CRS# outbuilding: S. 290.369 non-contributing
Property Address: 104 Beebe Avenue
Name of property: n/a
Date of property: n/a / outbuilding modern
Historic district: yes
Architectural details: mansard roof - pyramid roof. partial-width porch. lintel
pyramidal dormer with paired
windows. basement. block exterior.
Notes from secondary resources: .368 missing description in survey.
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-121
CRS# dwelling: 290.367 contributing
CRS# garage: n/a
Property Address: 106 Beebe Avenue
Name of property: n/a
Date of property: c. 1920
Historic district: yes
Architectural details: one-story dwelling with second-story attic. pediment dormer.
(r)
exterior brick chimney. screened-in full-width porch. paired double-hung windows
on r.
side.
Notes from secondary resources: 1992 survey describe raised-seam metal sheet roof.
No mention of screened-in porch.

Siding is no longer asphalt shingle.
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-9E
CRS# dwelling: 290.370 contributing
CRS# garage: 290.371 contributing
Property Address: 107 - 109 Beebe Avenue
Name of property: n/a
Date of property: c. 1920
Historic district: yes
Architectural details: mansard pyramidal roof. interior brick chimney. paired
windows on
façade. partial enclosed porch. double hung windows. aluminum exterior. shingle
roof -
asphalt. one-story hipped-roof unattached one-car garage.
Notes from secondary resources: rear is one-story shed roofed addition.
full-façade, one
story porch. #107 enclosed and louvered windows, #109 is open with square posts.
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-20
CRS# dwelling: S-290.365 contributing
CRS# garage: S-290.366 non-contributing
Property Address: 108 Beebe Avenue
Name of property: n/a
Date of property: c.1925 / garage early 20th C.
Historic district: yes
Architectural details: block foundation. two-story dwelling. full-width porch.
paired
windows. mansard pyramidal roof. shed dormer with paired stationary windows.
Unattached rear one-car garage.

Beebe Avenue

Notes from secondary resources: n/a
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-119
CRS# dwelling: S. 290.363 contributing
CRS# garage: S. 290.364 contributing
Property Address: 110 Beebe Avenue
Name of property: n/a
Date of property: 1919/ garage early 20th C.
Historic district: yes
Architectural details: block exterior. full-width screened-in porch, front gable roof. three rank facade.

two-story dwelling. rear shed. rear addition.
Notes from secondary resources: 1992 survey does not mention porch being screened in.
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-118
CRS# dwelling: 290.362 non-contributing
CRS# garage: n/a
Property Address: 112 Beebe Avenue
Name of property: n/a
Date of property: c. 1935
Historic district: yes
Architectural details: one-story dwelling. r side exterior cement chimney. partial

screened porch. side gable porch - shed like. pediment dormer.
Notes from secondary resources: extensively altered c. 1988.
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-100
CRS# dwelling: 290.373 contributing
CRS# garage: 290.374 contributing
Property Address: 113 Beebe Avenue
Name of property: n/a
Date of property: c. 1920
Historic district: yes
Architectural details: side gable roof. shed dormer with ribbon double-hung windows. one-story dwelling with

second-story attic. full-width porch with block foundation and column supports. paired windows - symmetrical.

front door with upper blank pane window.
unattached rear shed. raised block foundation.
Notes from secondary resources: Shed dormer with quad. Double-hung windows with blank panes. Full-width porch with

rock-faced paired posts.
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-117
CRS# dwelling: 290.360 contributing
CRS# garage: 290.361 non-contributing
Property Address: 114 Beebe Avenue
Name of property: n/a
Date of property: c. 1935 / modern garage
Historic district: yes

Beebe Avenue

Architectural details: side gable roof. one-story dwelling. paired symmetrical double-hung windows. front addition.
Notes from secondary resources: Porch is now wnclosed as part of the house with symmetrical paired double-hung

windows with blank panes.
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-101
CRS# dwelling: 290.375 contributing
CRS# garage: 290.376 contributing
Property Address: 115 Beebe Avenue
Name of property: n/a
Date of property: late 19th C. / garage early 20th C.
Historic district: yes
Architectural details: front gable roof. two-story dwelling with third-story attic.

full-width center-gable roof. porch with square column supports. interior brick ridge chimney. square balustrade with upper decorative brackets.
Notes from secondary resources: Porch is center gable roof not shed roofed as described. Porch no longer screened

in. Exterior is siding not asbestos shingle. Garage is two-car.
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-116
CRS# dwelling: 290.359 non-contributing
CRS# garage: n/a
Property Address: 116 Beebe Avenue (intrusion)
Name of property: n/a
Date of property: n/a
Historic district: n/a

Architectural details: wrap around porch. two-story dwelling. front gable roof with scalloped pattern in pediment. paired window on second floor. turn spindle porch supports. unattached rear shed.
Notes from secondary resources: n/a
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-104
CRS# dwelling: 290.377 contributing
CRS# garage: 290.378 contributing
Property Address: 117 Beebe Avenue
Name of property: n/a
Date of property: c. 1930 / garage early 20th C.
Historic district: yes

Architectural details: one-story dwelling. entry pediment porch with square porch supports. side gable roof.

double-hung windows with sill and lintel. unattached rear garage.
Notes from secondary resources: No gable screened in porch as described in 1992 survey.
Street survey completed: October 31, 2005

Tax Parcel #: n/a
CRS# dwelling: not on record
CRS# garage: n/a

Beebe Avenue

Property Address: 118 Beebe Avenue
Name of property: n/a
Date of property: n/a
Historic district: yes
Architectural details: Steep pitch roof. side gable roof form. wood shingle exterior.
facade does not face street.
Notes from secondary resources: No CRS number on record - 116 Beebe lot may have been split with 116 being the new house.
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-105
CRS# dwelling: 290.379 non-contributing
CRS# garage: n/a
Property Address: 119 Beebe Avenue (intrusion)
Name of property: n/a
Date of property: modern
Historic district: yes
Architectural details: one-story dwelling.
Notes from secondary resources: Outbuilding needs to be added to survey. Gambrel roof, small one-story shed with vertical sliding doors.
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-115
CRS# dwelling: 290.357 contributing
CRS# shed: 290.358 non-contributing
Property Address: 120 Beebe Avenue
Name of property: n/a
Date of property: c. 1910
Historic district: yes
Architectural details: side gable, steep-pitch roof. shed dormer with symmetrical, paired double-hung windows. full-width screened-in porch. double-hung, 2 by 2 sash windows. rear addition with shed roof. exterior wavy shingle.
Notes from secondary resources: domestic shed with shallow gable roof and plywood sheeting exterior finish.
Street survey completed: October 31, 2005

Tax Parcel #: 3-35-8.11-133.1
CRS# dwelling: 290.355 contributing
CRS# garage: 290.356 non-contributing
Property Address: 122 Beebe Avenue
Name of property: N/A
Date of property: c. 1900 / garage c. 1960
Historic district: yes
Architectural details: two-story dwelling. second-story overhang. porch enclosed. full-width porch with center gable roof. steep pitch dormer with triangular window. turn-spindle porch supports with turn-spindle balustrade. unattached garage.
Notes from secondary resources: n/a
Street survey completed: October 31, 2005

Beebe Avenue

Tax Parcel #: 3-35-8.11-113

CRS# dwelling: Not available

CRS# garage: N/A

Property Address: 124 Beebe Avenue

Name of property: N/A

Date of property: Not available

Historic district: Yes

Architectural details:

Notes from secondary resources: No longer in existence. May belong to 502 Kings Highway.

Street survey completed: October 31, 2005