

Fourth Street East

Tax Parcel # : 3-35-8.11-70
CRS # Dwelling: 290.407
CRS # Garage: N/A
Property Address: 106 East Fourth Street
Name of Property: N/A
Date of Property: Late 19th C.
Historic District?: Yes
Architectural Details: Center gable roof. Three-rank facade. Double-hung, two-over-two windows. Two stories with third-story attic. Peaked window. Full-width porch. Turn-spindle porch supports with decorative balustrade. Decorative brackets in porch supports. Ridge interior chimney.
Notes from Secondary Resources: Previously 108 East Fourth Street.
Street Survey Completed: August 2005

Tax Parcel # : 3-35-8.11-61
CRS # Dwelling: 290.408
CRS # Meat house: 290.409
Property Address: 107 East Fourth Street
Name of Property: N/A
Date of Property: Mid 19th C.
Historic District?: Yes
Architectural Details: Three-rank facade, symmetrical. Side gable roof. Wood shingle exterior. Wood door surround and window surround with sill. Double-hung, six-over-six windows. Left side interior brick ridge chimney. Metal roof. Rear addition pediment window surround.
Notes from Secondary Resources: Previously 105 East Fourth Street. 1992 survey described a screened porch that no longer exists, an asphalt shingle roof that is now metal, and no shutters.
Street Survey Completed: August 2005

Tax Parcel # : 3-35-8.11-59
CRS # Dwelling: 290.410 - Contributing
CRS # Carriage house: 290.411 - Contributing
Property Address: 109 East Fourth Street
Name of Property: N/A
Date of Property: c. 1882
Historic District?: Yes
Architectural Details: Side gable roof with paired ridge chimneys. Partial-width porch with shed roof. Porch supports chaffed with balustrade. Three-rank facade, symmetrical. Window surround with decorative lintel. Transom light in door surround. Wood shingle siding.
Notes from Secondary Resources: Since 1992 survey, changed exterior from aluminum siding to wood shingle, and windows from two-over-two sash to six-over-six sash.
Street Survey Completed: August 2005

Tax Parcel # : 3-35-8.11-73
CRS # Dwelling: 290.405 - Contributing
CRS # Outbuilding: 290.406 - Non-contributing
Property Address: 110 East Fourth Street
Name of Property: N/A
Date of Property: c. 1925 for dwelling / c. 1960 for outbuilding
Historic District?: Yes
Architectural Details: Pyramidal hipped roof with dormers. Paired casement window in dormer. Symmetrical, blank-pane second-story windows. Double-hung windows. Full-width porch. Square porch supports and balustrade.
Notes from Secondary Resources: N/A
Street Survey Completed: August 2005

Tax Parcel # : 3-35-8.11-58
CRS # Dwelling: 290.412 - Contributing
CRS # Garage: 290.413 - Non-contributing
Property Address: 113 East Fourth Street
Name of Property: N/A

Fourth Street East

Date of Property: Late 19th C. for dwelling / modern garage
Historic District?: Yes

Architectural Details: Side gable roof form. Two-by-two frame (two deep by two wide). Symmetrical window placement on second floor. Full-width porch with turn-spindle supports. Decorative balustrade and brackets in porch supports. Wood shingle exterior. Shingle roof. Shutters. Rear addition.

Notes from Secondary Resources: Metal roof noted in 1992 survey is now shingle.
Street Survey Completed: August 2005

Tax Parcel # : 3-35-8.11-74

CRS # Dwelling: 290.404 - Contributing

CRS # Garage: N/A

Property Address: 114 East Fourth Street

Name of Property: N/A

Date of Property: Late 19th C.

Historic District?: Yes

Architectural Details: Side gable roof. Three-rank facade, asymmetrical. Double-hung, two-over-two windows. Transom light in door surround. Full-width screened porch. Porch has wide eave overhangs with decorative brackets.

Notes from Secondary Resources: N/A
Street Survey Completed: August 2005

Tax Parcel # : 3-35-8.11-57

CRS # Dwelling: Not available

CRS # Garage: N/A

Property Address: 115 East Fourth Street

Name of Property: N/A

Date of Property: Modern

Historic District?: Yes

Architectural Details: New home intrusion. Cross gable roof form. Full-width porch with square supports and balustrade. Aluminum shingle exterior. Fish-scale pattern in gable. Two-story bay window on facade with double-hung windows.

Notes from Secondary Resources: No CRS number on record. Cross reference: Located on a part of 160 Kings Highway Land, CRS # 290.414 and 290.415.
Street Survey Completed: August 2005

Tax Parcel # : 3-35-8.11-75

CRS # Dwelling (Stable): 290.403 - Contributing

CRS # Garage: N/A

Property Address: 118 East Fourth Street

Name of Property: N/A

Date of Property: Not available

Historic District?: Yes

Architectural Details: Symmetrical, three-rank facade. Side gable roof. Six-over-six, double-hung windows with shutters. Partial-width porch with square supports. Decorative balustrade and brackets in porch supports. Wood shingle exterior (painted or aluminum). Center passage door with three-pane transom light in door surround.

Notes from Secondary Resources: Listed as a stable in 1992 survey. Needs new survey.
Street Survey Completed: August 2005