

Franklin Avenue

Tax Parcel # : 3-35-8.08-88

CRS # Dwelling: 290.112 - Contributing

CRS # Outbuilding: 290.113 - Contributing

Property Address: 107 Franklin Avenue

Name of Property: N/A

Date of Property: c. 1940

Historic District?: Yes

Architectural Details: One-story dwelling with attic and three bays. Center gable roof. Enclosed pediment entry. Bracket on windows. Double-hung windows. Right side separate entrance. Rear outbuilding.

Notes from Secondary Resources: N/A

Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.08-87

CRS # Dwelling: Not available

CRS # Garage: N/A

Property Address: 111 Franklin Avenue

Name of Property: N/A

Date of Property: Not Available

Historic District?: Yes

Architectural Details: No longer in existence. Now the Lewes Police Department parking lot.

Notes from Secondary Resources: N/A

Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.08-78

CRS # Dwelling: 290.141 - Contributing

CRS # Garage: N/A

Property Address: 112 Franklin Avenue

Name of Property: N/A

Date of Property: Late 19th C

Historic District?: Yes

Architectural Details: Two-story, two-bay home. Rear addition. Double-hung, two-over-two sash windows. Wooden window surround with sill and lintel. Central ridge chimney. Front gable roof with decorative verge boards. Moderate eave overhangs with decorative brackets. Full-width porch with central gable roof. Decorative turn-spindle porch supports with square balustrade. Double-hung attic window. door surround. Siding (80s or 70s).

Notes from Secondary Resources: N/A

Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.08-86

CRS # Dwelling: 290.116 - Contributing

CRS # Shed: 290.117 - Contributing

Property Address: 115 Franklin Avenue

Name of Property: N/A

Date of Property: c. 1880 for dwelling / Late 19th C. for shed.

Historic District?: Yes

Architectural Details: Two-story. Side gable roof. Three-bay facade. Double-hung, two-over-two sash windows. Asymmetrical window and door placement. Second front door. Decorative window surround. Transom light in door surround.

Notes from Secondary Resources: N/A

Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.08-85

CRS # Dwelling: 290.118 - Contributing

CRS # Shed: 290.119 - Non-contributing

Property Address: 119 Franklin Avenue

Name of Property: N/A

Date of Property: Early 20th C. for dwelling / Late 19th C. for shed

Historic District?: Yes

Architectural Details: One-story dwelling. Wooden siding. Side gable roof. Full-facade, screened porch with front gable roof. Rear addition, two story.

Franklin Avenue

Double-hung windows. Left side exterior brick chimney.
Notes from Secondary Resources: Heavily altered in 1980s. Allegedly part of an old coast guard station.
Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.08-84
CRS # Dwelling: 290.120 - Contributing
CRS # Garage: 290.121 - Contributing
Property Address: 121 Franklin Avenue
Name of Property: N/A
Date of Property: c. 1890 for dwelling / early 20th C. for garage
Historic District?: Yes
Architectural Details: Two-story front gable with attic. Full-width porch with shed roof. Wood shingle exterior. Two-bay asymmetrical facade. Rear addition. Wooden window surround with lintel. Moderate eave boxed overhangs.
Notes from Secondary Resources: N/A
Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.08-80
CRS # Dwelling: 290.138 - Contributing
CRS # Shed: 290.139 - Contributing
Property Address: 122 Franklin Avenue
Name of Property: N/A
Date of Property: Late 19th C.
Historic District?: Yes
Architectural Details: Two-bay, two-story dwelling. Double-hung windows. Front gable roof with moderate boxed eave overhangs. Full-width porch with center gable roof. Rear brick ridge interior chimney. Shutters. Rear addition.
Notes from Secondary Resources: N/A
Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.08-83
CRS # Dwelling: 290.122 - Contributing
CRS # Garage: N/A
Property Address: 125 Franklin Avenue
Name of Property: N/A
Date of Property: c. 1890
Historic District?: Yes
Architectural Details: Two-story, three-bay facade with side-gabled roof. Double-hung, six-over-six windows. wide wooden window surround with shutters. Transom light in door surround. Glass-paned door. Entry porch with pediment roof and column supports. Wood shingle exterior. Rear addition (maybe two times).
Notes from Secondary Resources: Additions include one-story lean-to on the wing south east elevation with a second story, flat roofed addition above. Attached to the rear elevation is a one-story gable-roofed pseudo summer kitchen. Changed windows from two-over-two sash to six-over-six with shutters.
Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.12-16
CRS # Dwelling: 290.137 - Contributing
CRS # Garage: N/A
Property Address: 126 Franklin Avenue
Name of Property: N/A
Date of Property: Late 19th C
Historic District?: Yes
Architectural Details: Two-story with attic and front gable roof. Front changed to side of house. Double-hung windows. Second-story screened overhang porch. Rear addition. Vinyl siding with shutters.
Notes from Secondary Resources: Changed windows on first-floor main facade from one-over-one to twelve-over-twelve. Siding is either aluminum or weatherboard. The gable still has wavy asbestos.
Street Survey Completed: 29 August 2005

Franklin Avenue

Tax Parcel # : 3-35-8.08-82
CRS # Dwelling: 290.123 - Non-contributing
CRS # Garage: 290.124 - Non-contributing
Property Address: 129 Franklin Avenue
Name of Property: N/A
Date of Property: c 1950 for dwelling / garage not available
Historic District?: Yes
Architectural Details: Brick exterior. One-story dwelling. Paired double-hung, blank-pane windows. Dormer on roof. Left side exterior brick chimney. Basement. Rear, one-car garage with cement block exterior.
Notes from Secondary Resources: No garage on 1992 survey.
Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.12-17
CRS # Dwelling: 290.135 - Non-contributing
CRS # Utility outbuildings: 290.136 - Contributing
Property Address: 130 Franklin Avenue
Name of Property: N/A
Date of Property: c. 1950
Historic District?: Yes
Architectural Details: One-story double wide. Double-hung windows with shutters. Ranch style. Out building has metal exterior.
Notes from Secondary Resources: N/A
Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.08-81
CRS # Dwelling: 290.125 - Contributing
CRS # Garage: 290.126 - Non-contributing
Property Address: 131 Franklin Avenue
Name of Property: N/A
Date of Property: c. 1900
Historic District?: Yes
Architectural Details: Front gable, two-story dwelling. One-bay symmetrical. Door on first floor. Full-width porch with turn-spindle column supports. Six-pane front door. Double-hung, six-over-blank windows in front. Metal roof on home and porch. Addition to side - enclosed porch. Concrete rear slope interior chimney. Garage in rear (outbuilding).
Notes from Secondary Resources: N/A
Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.12-18
CRS # Dwelling: 290.134 - Contributing
CRS # Garage: N/A
Property Address: 132 Franklin Avenue
Name of Property: N/A
Date of Property: Late 19th C
Historic District?: Yes
Architectural Details: Two-story with side gable roof. Three-rank symmetrical facade. wide window surround with sill and shutters. Transom light in door surround. Partial-width porch with turn-spindle supports.
Notes from Secondary Resources: Exterior does not seem to be wood shingles but weatherboard.
Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.12-22
CRS # Dwelling: 290.127 - Contributing
CRS # Garage: N/A
Property Address: 135 Franklin Avenue
Name of Property: N/A
Date of Property: c. 1885
Historic District?: Yes
Architectural Details: Three-rank facade. Wood shingle exterior. Side gable roof - shingle. Asymmetrical window and door placement. Full-width porch with

Franklin Avenue

turn-spindle column supports. Square balustrade. Transom light in door surround. Decorative brackets in porch supports. Double-hung, two-over-two windows. Rear Addition.

Notes from Secondary Resources: Wing is one and one-and-a-half stories and has a paired interior gable-end chimney. Previously had metal roof.

Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.12-19

CRS # Dwelling: 290.132 - Contributing

CRS # Garage: 290.133 - Non-contributing

Property Address: 136 Franklin Avenue

Name of Property: N/A

Date of Property: c. 1920 for dwelling / modern garage

Historic District?: Yes

Architectural Details: Pyramid hipped roof and dormer with paired windows.

Three-bay, one-story dwelling. Double-hung, eight-over-blank windows. Full-width porch with classic column supports. Turn-spindle balustrade porch. Cement

foundation with basement windows. Wide eave overhangs. One-car garage in rear.

Notes from Secondary Resources: N/A

Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.12-23

CRS # Dwelling: 290.128 - Contributing

CRS # Garage: N/A

Property Address: 137 Franklin Avenue

Name of Property: N/A

Date of Property: Late 19th C

Historic District?: Yes

Architectural Details: Side gable roof form. Two-story with attic. Three-rank,

asymmetrical facade. full-width porch with classic column porch supports and balustrade. Decorative brackets in porch supports. Vinyl siding. Double-hung,

blank-pane windows. Moderate eave overhangs. Side and rear addition.

Notes from Secondary Resources: Additions include a 20th century, one-story gable roofed summer kitchen built over an existing shed-roofed mud room on the wing gable

end, and a shed roofed addition on the south east gable end with second story projecting gable roofed bay. Dwelling's previous metal roof replaced with shingle.

Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.12-20

CRS # Dwelling: 290.130 - Contributing

CRS # Utility outbuilding: 290.131 - Contributing

Property Address: 138 Franklin Avenue

Name of Property: N/A

Date of Property: Late 19th C. for dwelling / early 20th C. for outbuilding

Historic District?: Yes

Architectural Details: One-story dwelling with attic. Double-hung, six-over-blank pane windows. Wood shingle exterior. Front gable roof. Full-width enclosed porch.

Bratton door on door. Side addition.

Notes from Secondary Resources: Windows now six-over-one instead of one-over-one in gable.

Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.12-24

CRS #: none on record

Property Address: 141 Franklin Avenue

Name of Property: N/A

Date of Property: not noted

Historic District?: Yes

Architectural Details: two-story dwelling. wide window surround. partial

wrap-around porch with decorative board balustrade. shed dormer. paired, double-hung windows. decorative-pane front door. fish-scale pattern in gable.

Notes from Secondary Resources: n/a

Franklin Avenue

Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.12-12

CRS # Dwelling: 290.129 - Contributing

CRS # Garage: N/A

Property Address: 142 Franklin Avenue

Name of Property: N/A

Date of Property: Mid 19th C

Historic District?: Yes

Architectural Details: Side gable roof form. Two story with attic. Three-rank symmetrical facade. Double-hung, blank-pane windows. Wood shingle exterior.

Window and door surround. Front door nine partial panes. Full-width porch with column supports and square balustrad. Shed roofed. Has rear addition.

Notes from Secondary Resources: 1992 survey noted windows were three-over-three, exterior was T-11 board and novelty board, and there was no mention of porch.

Street Survey Completed: 29 August 2005

Tax Parcel # : 3-35-8.12-26

CRS #: none on record

Property Address: 201 Franklin Avenue

Name of Property: N/A

Date of Property: not noted

Historic District?: not noted

Architectural Details: two-story home with wood shingle exterior. Located next to railroad tracks. side gable roof. wooden window surround. double-hung, blank-pane windows. three-by-five, three-pane casement attic window. two-story, wooden porch overhang. moderate eave overhangs.

Notes from Secondary Resources: n/a

Street Survey Completed: 29 August 2005