

Shi pcarpenter Street

Tax Parcel #: 3-35-8.07-308

CRS # Dwelling: 290.697 contributing

Property Address: 105 Shipcarpenter Street

Name of property: 1740 Arsenal Site

Date of property: 19th c.

Historic district: yes

Architectural details: two story. original front on Second Street. asymmetrical window/door placement. double-hung windows with wood surround. third-story attic window. entry porch with turn-spindle posts. bay palladian window.

Notes from secondary resources: original nomination #27. said to have stand on War of 1812 Arsenal site. Several additions since 1992 survey.

Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-283

CRS # Dwelling: 290.295 contributing

CRS # Garage: 290.296 contributing

Property Address: 106 Shipcarpenter Street

Name of property: n/a

Date of property: early 20th c.

Historic district: yes

Architectural details: front gable roof, two-story dwelling. two-story bay windows with various double-hung sash windows - one-over-one, two-over-one, and six-over-one. steep pitch roof. exterior rear chimney. shingle exterior. entry pediment roof with triangle bracket supports. left side addition.

Notes from secondary resources: original nomination #83. Differences to 1992 survey: no garage but a rear unattached one-story shed.

Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-288

CRS # Dwelling: 290.762 contributing

CRS # Garage: 290.763 contributing

Property Address: 209 Shipcarpenter Street

Name of property: n/a

Date of property: c. 1930 - dwelling

Historic district: yes

Architectural details: side gable roof with steep pitch. full-facade glass enclosed porch. wide dormer with ribbon double-hung, three-over-one windows. transom light in door surround. double-hung windows with wood surround. wide eave overhang with exposed rafter feet. shingle exterior. rear addition: two story with gable roof.

Notes from secondary resources: original nomination #86.

Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-289.1

CRS # Dwelling: 290.764 contributing

Property Address: 234 Shipcarpenter Street

Name of property: n/a

Date of property: c. 1935

Historic district: yes

Architectural details: full-width enclosed porch. double-hung, six-over-one windows. gable dormer with ribbon double-hung, six-over-one windows. shingle exterior. side lights in door surround. paired windows on first floor.

Notes from secondary resources: original nomination #86. Since 1992 survey, siding changed from aluminum to shingle.

Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-250 or 256

CRS # Dwelling: 290.659 non-contributing

Property Address: 305 Shipcarpenter Street

Name of property: n/a

Date of property: modern

Historic district: yes

Architectural details: gambrel roof. full-facade porch - upper second level screened in.

Shi pcarpenter Street

Notes from secondary resources: original nomination #87. the 1992 survey described a modern small frame dwelling, not so at all. instead, a two-story dwelling with gable front roof with a second story screened porch.
Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-251

CRS # Dwelling: 290.660 contributing

Property Address: 307 Park Avenue / Shi pcarpenter Street

Name of property: n/a

Date of property: late 19th c

Historic district: yes

Architectural details: two-story, front-gable dwelling. pediment entry visor with tooth-like decoration. double-hung, six-over-six windows. shutters on first floor only. third floor attic with decorative lintel and double-hung six-over-blank-pane window. wood shingle exterior. batten doors. bell tower on pitch of roof.

Notes from secondary resources: original nomination #88.

Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-252.1

CRS # Dwelling: 290.661 contributing

CRS # Shed: 290.662 contributing

Property Address: 309 Park Avenue / Shi pcarpenter Street

Name of property: n/a

Date of property: late 19th c.

Historic district: yes

Architectural details: side gable roof. symmetrical three-bay facade. slope interior chimney. paired windows on first floor. double-hung, six-over-six windows on second floor. moderate eave overhangs with decorative brackets.

Notes from secondary resources: original nomination #89. No mention of rear screened-in porch on 1992 survey.

Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-252

CRS # Dwelling: 290.663 contributing

Property Address: 311 Park Avenue / Shi pcarpenter Street

Name of property: n/a

Date of property: c. 1935

Historic district: yes

Architectural details: intrusion. one-story dwelling with hipped pyramidal roof.

Notes from secondary resources: n/a

Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-255

CRS # Dwelling: 290.666 contributing

Property Address: 313 Park Avenue / Shi pcarpenter Street

Name of property: n/a

Date of property: 1904 - 1910

Historic district: yes

Architectural details: sits way back from street.

Notes from secondary resources: n/a

Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-254

CRS # Dwelling: 290.664

Property Address: 315 Park Avenue / Shi pcarpenter Street

Name of property: n/a

Date of property: not noted

Historic district: yes

Architectural details: side gable roof. pediment door surround. double-hung, six-over-six windows with shutters. wood siding exterior. exterior chimney. cement foundation.

Notes from secondary resources: was a vacant lot when 1992 survey done.

Street survey completed: 1 November 2005

Shi pcarpenter Street

Tax Parcel #: 3-35-8.07-256
CRS # Church: 290.667 contributing
CRS # Dwelling: 290.668 non-contributing
Property Address: 317 Shi pcarpenter Street
Name of property: Saint George AME Church est. 1816
Date of property: 1930 - church / c. 1970 - dwelling
Historic district: yes
Architectural details: not noted
Notes from secondary resources: original nomination #92.
Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-257
CRS # Dwelling: 290.669 contributing
CRS # Shed: 290.670 contributing
Property Address: 321 Park Ave / Shi pcarpenter Street
Name of property: n/a
Date of property: c. 1930 - dwelling / early 20th c. - shed
Historic district: yes
Architectural details: two-story dwelling. second floor in roof. side gable roof. shed dormer. enclosed porch addition to front with paired windows.
Notes from secondary resources: could be the same since 1992 survey, but picture should be checked.
Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-258
CRS # Dwelling: 290.671 contributing
Property Address: 323 Park Avenue / Shi pcarpenter Street
Name of property: n/a
Date of property: 1904
Historic district: yes
Architectural details: two-story dwelling. two-bay facade. full-width porch with square wood supports. decorative brackets in eave porch overhangs. central ridge interior chimney. rear one-story addition.
Notes from secondary resources: n/a
Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-259
CRS # Dwelling: 290.672 non-contributing
Property Address: 329 Park Avenue
Name of property: n/a
Date of property: c. 1980
Historic district: yes
Architectural details: side gable roof. three-bay facade. double-hung windows, six-over-six on second floor and eight-over-twelve on first floor. enclosed entry with transom light. wood shingle exterior. brick foundation. left side two-story addition with dormers and chimney.
Notes from secondary resources: former site of Saint Paul's M. E. Church. The 1992 survey did not mention enclosed entry or left side addition which makes the facade five-bay.
Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-260
CRS # Dwelling: 290.673 contributing
Property Address: 331 Park Ave
Name of property: n/a
Date of property: c. 1910
Historic district: yes
Architectural details: two story dwelling side gable roof. ridge interior chimney. full width enclosed porch. double-hung windows.
Notes from secondary resources: original nomination #94. enclosed shed roofed porch since 1992 survey.
Street survey completed: 1 November 2005

Shi pcarpenter Street

Tax Parcel #: 3-35-8.07-261

CRS # Dwelling: 290.674 contributing

Property Address: 335 Park Avenue

Name of property: n/a

Date of property: 1904 - 1910

Historic district: yes

Architectural details: one story dwelling. full-width porch with roof overhang. front gable roof. turn-spindle porch supports. paired windows to the left of door. casement window to right.

Notes from secondary resources: original nomination #94. this may be a new home - 1992 survey picture should be checked.

Street survey completed: 1 November 2005

Tax Parcel #: 3-35-8.07-266

CRS # Dwelling: 290.675 contributing

Property Address: 339 Park Ave / W. Fourth Street

Name of property: n/a

Date of property: c. 1880

Historic district: yes

Architectural details: side gable roof. one-and-a-half story. second floor in roof. shed dormers with double-hung windows. window surround and shutters. wood shingle siding. left side addition: one-story with shed roof and wrap-around filling in the ell.

Notes from secondary resources: original nomination #94.

Street survey completed: 1 November 2005