

Washington Avenue

Tax Parcel #: not noted

CRS #: none

Property Address: 108 Washington Avenue

Name of property: n/a

Date of property: not noted

Historic district: yes

Architectural details: front gable two-story dwelling. wood shingle. double-hung, eight-over-eight sash windows. partial-width porch with shed roof. rear hipped roof shed.

Notes from secondary resources: front being remodeled.

Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-40

CRS # Dwelling: 290.172 contributing

Property Address: 110 Washington Avenue

Name of property: n/a

Date of property: c. 1890

Historic district: yes

Architectural details: side gable roof. two story with attic. double-hung, two-over-two windows. transom light in door surround. turn-spindle column porch supports with square balustrade. left side exterior brick chimney. full-width porch with decorative brackets in eave overhang. rear addition: shed roof addition on south east elevations.

Notes from secondary resources: n/a

Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-39

CRS # Dwelling: 290.170 contributing

CRS # Garage: 290.171 contributing

Property Address: 112 Washington Avenue

Name of property: n/a

Date of property: c. 1910 - dwelling / early 20th c. - garage

Historic district: yes

Architectural details: front gable porch. two story with attic. double-hung, blank-pane windows. wrap-around porch, partial width with column supports. unattached garage in rear.

Notes from secondary resources: n/a

Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-8

CRS # Dwelling: 290.149 contributing

Property Address: 113 Washington Avenue

Name of property: n/a

Date of property: c. 1885

Historic district: yes

Architectural details: three story Italianate home with mansard roof. pediment dormers in roof. window surround with sill and lintel. full width porch with chamfered supports. transom light in door surround. decorative brackets in porch supports. two-over-two, double-hung windows. fish-scale pattern in roof. rear addition.

Notes from secondary resources: since 1992 survey: siding now weatherboard not wavy asbestos and rear addition's roof looks like a mansard.

Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-9

CRS # Dwelling: 290.150 contributing

CRS # Garage: 290.151 contributing

Property Address: 115 Washington Avenue

Name of property: n/a

Date of property: c. 1890 - dwelling / early 20th c. - garage

Historic district: yes

Architectural details: central gable roof with steep pitch. partial-width, screened porch. six-over-six, double-hung windows. window surround. exterior cement

Washington Avenue

chimney. rear addition: one story with shed roof. rear outbuilding: shed attached to home.

Notes from secondary resources: since 1992 survey: windows replaced, exterior now vinyl with corner boards from asbestos shingle.

Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-38

CRS # Dwelling: 290.169 contributing

Property Address: 116 Washington Avenue

Name of property: n/a

Date of property: c. 1890

Historic district: yes

Architectural details: side gable roof. two story with attic. double-hung, six-over-six windows. three-rank symmetrical facade. entry porch with turn-spindle supports. one-story visor from porch. wooden window surround and shutters.

transom light in door surround. wood shingle exterior. rear addition.

Notes from secondary resources: since 1992 survey: transom light now flat panel not three.

Street survey completed: September 2005

Tax Parcel #: not noted

CRS #: none on record

Property Address: 118 Washington Avenue

Name of property: n/a

Date of property: not noted

Historic district: yes

Architectural details: center gable roof with steep pitch. peaked window in attic. wooden window surround. double-hung, blank-pane windows. partial-width screened porch. wood siding. side light in door surround on right side only. rear

addition.

Notes from secondary resources: n/a

Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-10

CRS # Dwelling: 290.152 contributing

Property Address: 119 Washington Avenue

Name of property: n/a

Date of property: late 19th c.

Historic district: yes

Architectural details: side gable roof. three-rank symmetrical facade. wooden window surround with sill and shutters. transom light in door surround.

double-hung, six-over-nine windows. double ended chimneys, one interior and one exterior. wood shingle exterior. rear addition: two-story, gable-roofed wing. to the southeast of this wing is a one-story, shed-roofed addition. further back is a connected modern two-story, gable-roofed addition. the second story is living space and first story is a two-car garage.

Notes from secondary resources: n/a

Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-11

CRS # Dwelling: 290.153 contributing

CRS # Garage: 290.154 contributing

Property Address: 125 Washington Avenue

Name of property: n/a

Date of property: early 20th c.

Historic district: yes

Architectural details: side gable roof with pediment dormer. front slope interior brick chimney. front facade faces right instead of street. double-hung windows.

paired, six-over-blank-paned windows on second floor and attic. blank-pane windows on first floor. screened porch with second floor access. bay window on right side.

pattern shingle in gable facing street.

Notes from secondary resources: n/a

Street survey completed: September 2005

Washington Avenue

Tax Parcel #: 3-35-8.12-36  
CRS # Dwelling: 290.166 contributing  
Property Address: 126 Washington Avenue  
Name of property: n/a  
Date of property: c. 1935

Historic district: yes  
Architectural details: two-story dwelling with pyramidal hipped roof and symmetrical facade. paired windows on left and right sides with one single window in middle. decorative window surround. pediment entry visor porch. wide eave overhangs. rear slope interior chimney. double-hung, six-over-blank-pane windows. side addition: one-story, hip-roofed addition on northwest elevation which wraps around to rear elevation.

Notes from secondary resources: n/a  
Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-35  
CRS # Dwelling: 290.164 contributing  
CRS # Garage: 290.165 contributing  
Property Address: 128 Washington Avenue  
Name of property: n/a  
Date of property: c. 1890 - house / early 20th c. - garage

Historic district: yes  
Architectural details: side gable roof. wood shingle exterior. three-rank symmetrical facade. double-hung, six-over-blank-pane windows. partial nine pane door. entry porch with pilaster supports and central pediment roof with visor (shingle). pilaster door surround. wooden window surround. rear addition. shed roof addition filling in the ell. some details suggest a c. 1930 colonial revival treatment.

Notes from secondary resources: since 1992 survey: exterior is shingle not wavy asbestos. garage has shingle siding and roof, no longer vertical board siding or metal roof.  
Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-12  
CRS # Dwelling: 290.155 contributing  
Property Address: 129 Washington Avenue  
Name of property: n/a  
Date of property: late 19th c.

Historic district: yes  
Architectural details: two story. side gable roof with attic. three-rank asymmetrical facade. right side interior ridge chimney. decorative turn-spindle column supports and square balustrades. partial-width porch. shutters on front windows. two rear additions. to the rear is a two-story, gable-roofed wing, a one-story, gable-roofed wings, and a two-story shed to the southeast.

Notes from secondary resources: since 1992 survey: porch not partial or enclosed.  
Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-34  
CRS # Dwelling: 290.163 contributing  
Property Address: 130 Washington Avenue  
Name of property: n/a  
Date of property: c. 1890

Historic district: yes  
Architectural details: side gable roof. two story with attic and skylight. stucco exterior. full-width screened porch with central gable roof. window surround with sill. double-hung windows with blank panes.

Notes from secondary resources: one-and-a-half-story lean-to addition on the wing gable end.  
Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-13  
CRS # Dwelling: 290.156 contributing

Washington Avenue

CRS # Garage: 290.157 contributing  
CRS # Shed: 290.158 contributing  
CRS # Garage: 290.159 contributing  
Property Address: 131 Washington Avenue  
Name of property: n/a  
Date of property: late 19th c. house & shed / early 20th c. both garages  
Historic district: yes  
Architectural details: two story. side gable roof. three-rank symmetrical facade. double-hung, two-over-two windows with wooden surround and sill. partial-pane door with wooden surround. wood siding exterior. wrap-around porch partially screened. square porch supports and balustrade. rear addition. arched windows.  
Notes from secondary resources: since 1992 survey: porch is only partially enclosed. only one garage exists. survey descriptions are similar for both garages, the existing one is one-story, gable-roofed with vertical weatherboard siding. cannot see if there is a one-story shed-roof utility shed.  
Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-33  
CRS # Dwelling: 290.161 contributing  
CRS # Summer Kitchen: 290.162 contributing  
Property Address: 132 Washington Avenue  
Name of property: n/a  
Date of property: c. 1910 house / c. 1890 kitchen  
Historic district: yes  
Architectural details: side gable roof. three-rank, symmetrical facade. entry visor and bracket tops over windows. moderate eave overhangs. double-hung, blank-pane windows. siding (70s or 80s).  
Notes from secondary resources: two-story, gable-roofed wing built in the 1930s.  
Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-32  
CRS # Dwelling: 290.160 contributing  
Property Address: 134 Washington Avenue  
Name of property: n/a  
Date of property: c. 1890  
Historic district: yes  
Architectural details: two story. side gable roof. pediment dormer with decorative pattern in gable and ribbon, double-hung windows with pediment surround. wide eave boxed overhangs. double-hung, two-over-two windows with pediment surrounds. door surround with pane indoor. partial -width porch with square column supports and balustrade. left-side, two-story addition.  
Notes from secondary resources: n/a  
Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-31  
CRS #: not noted  
Property Address: 136 Washington Avenue  
Name of property: n/a  
Date of property: not noted  
Historic district: yes  
Architectural details: two story side gable roof with attic. entry porch with pediment roof and turn column supports and fish scale pattern. decorative door surround with dentil molding. two rank asymmetrical facade. wood shingle exterior. double-hung, blank-pane windows. rear addition and shed in rear of property. two story added entry.  
Notes from secondary resources: n/a  
Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-30  
CRS #: not noted  
Property Address: 138 Washington Avenue  
Name of property: n/a  
Date of property: not noted

Washington Avenue

Historic district: yes

Architectural details: gambrel roof with shed dormers (metal top roof). entry visor over door. double-hung, six-over-six windows. side slope interior chimney. vertical wood siding. rear addition.

Notes from secondary resources: n/a

Street survey completed: September 2005

Tax Parcel #: 3-35-8.12-29

CRS #: not noted

Property Address: 140 - 142 Washington Avenue

Name of property: n/a

Date of property: not noted

Historic district: yes

Architectural details: two story town home. four bay symmetrical. wooden window surround. decorative door surround with pilaster-like look. dentil molding above door. dentil decorative molding in eave overhang. side gable metal roof. 142 has first story visor.

Notes from secondary resources: n/a

Street survey completed: September 2005